

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/28/2020

Submitted Date:

01/28/2020

Document Number:

689704118

FIELD INSPECTION FORMLoc ID 335607 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

20 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282086	WELL	PR	10/14/2009	GW	045-11643	N. PARACHUTE EF06D L29 595	PR
282087	WELL	PR	08/16/2007	GW	045-11642	N. PARACHUTE EF06B L29 595	PR
282089	WELL	PR	04/26/2008	GW	045-11641	N. PARACHUTE EF03D-32 L29 59	PR
282090	WELL	PR	08/21/2007	GW	045-11640	N.PARACHUTE EF03D L29 595	PR
282091	WELL	PR	11/01/2012	GW	045-11644	N. PARACHUTE EF04D-32 L29 59	PR
282092	WELL	PR	11/01/2012	GW	045-11639	N. PARACHUTE EF12B L29 595	PR
282095	WELL	PR	11/01/2012	GW	045-11638	N.PARACHUTE EF13B L29 595	PR
282096	WELL	PR	02/01/2014	GW	045-11637	N.PARACHUTE EF05B-32 L29 59	PR
282097	WELL	PR	08/21/2007	GW	045-11636	N.PARACHUTE EF06B-32 L29 59	PR
282098	WELL	PR	01/25/2007	GW	045-11635	N.PARACHUTE EF06C-32- L29 59	PR
282102	WELL	PR	04/03/2007	GW	045-11650	N.PARACHUTE EF04B L29 595	PR
282103	WELL	PR	04/03/2007	GW	045-11649	N.PARACHUTE EF05B L29 595	PR
282104	WELL	PR	04/03/2007	GW	045-11648	N.PARACHUTE EFO6D-32 L29 59	PR
282105	WELL	PR	04/03/2007	GW	045-11647	N.PARACHUTE EF13D L29 595	PR

282106	WELL	PR	02/14/2007	GW	045-11646	N.PARACHUTE EF03C L29 595	PR
282107	WELL	PR	08/16/2007	GW	045-11645	N.PARACHUTE EF06A-32 L29 59	PR

General Comment:

This is a summary of inspection report.

On Tuesday 01/28/2020 at approximately 1440 hours, I, Inspector Mike Longworth, conducted a field inspection at CAERUS PICEANCE LLC N. PARACHUTE-65S95W 29NWSW, at Location # 335607 in Garfield County, Colorado

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 16		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	282086	Type:	WELL	API Number:	045-11643	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282087	Type:	WELL	API Number:	045-11642	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282089	Type:	WELL	API Number:	045-11641	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282090	Type:	WELL	API Number:	045-11640	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282091	Type:	WELL	API Number:	045-11644	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282092	Type:	WELL	API Number:	045-11639	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282095	Type:	WELL	API Number:	045-11638	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282096	Type:	WELL	API Number:	045-11637	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	282097	Type:	WELL	API Number:	045-11636	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282098	Type:	WELL	API Number:	045-11635	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282102	Type:	WELL	API Number:	045-11650	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282103	Type:	WELL	API Number:	045-11649	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282104	Type:	WELL	API Number:	045-11648	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282105	Type:	WELL	API Number:	045-11647	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282106	Type:	WELL	API Number:	045-11646	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282107	Type:	WELL	API Number:	045-11645	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
		Culverts	Pass			
Compaction	Pass					
Ditches	Pass					
				Material Handling And Spill Prevention	Pass	
		Compaction	Pass			

Comment: Limited BMP inspection due to snow cover.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689704119	Inspection 689704118 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5051046