

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/28/2020

Submitted Date:

01/28/2020

Document Number:

689704122

FIELD INSPECTION FORM

Loc ID 335807 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

30 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280531	WELL	PR	10/08/2006	GW	045-11277	N.PARACHUTE EFO6B I30A 595	PR
280532	WELL	PR	10/06/2006	GW	045-11278	N.PARACHUTE EF06D I30A 595	PR
280533	WELL	PR	02/01/2011	GW	045-11279	N.PARACHUTE EF07B I30A 595	PR
280534	WELL	PR	08/15/2006	GW	045-11280	N.PARACHUTE EF07D I30A 595	PR
280535	WELL	PR	08/11/2006	GW	045-11281	N.PARACHUTE EF01B I30A 595	PR
280536	WELL	PR	08/14/2006	GW	045-11282	N.PARACHUTE EF02B I30A 595	PR
280537	WELL	PR	08/11/2006	GW	045-11283	N.PARACHUTE EF02D I30A 595	PR
280538	WELL	PR	09/27/2006	GW	045-11284	N.PARACHUTE EF03D I30A 595	PR
293553	WELL	PR	08/09/2008	GW	045-15048	N. PARACHUTE EF05A-32 I30A 5	PR
293554	WELL	PR	10/13/2008	GW	045-15049	N. PARACHUTE EF05C-32 I30A 5	PR
293555	WELL	PR	03/27/2008	GW	045-15050	N. PARACHUTE EF04C-32 I30A 5	PR
293556	WELL	PR	09/19/2007	GW	045-15051	N. PARACHUTE EF02C-30 I30A 5	PR
293557	WELL	PR	02/01/2011	GW	045-15047	N. PARACHUTE EF16A-30 I30A 5	PR
293558	WELL	PR	08/09/2008	GW	045-15046	N. PARACHUTE EF02A-30-I30A 5	PR

293559	WELL	PR	11/19/2007	GW	045-15059	N. PARACHUTE EF15D-19 I30A 5	PR
293560	WELL	PR	08/14/2009	GW	045-15060	N. PARACHUTE EF15C-19 I30A 5	PR
293680	WELL	PR	10/13/2008	GW	045-15096	N. PARACHUTE EF03C-30 I30A 5	PR
293681	WELL	PR	10/06/2008	GW	045-15097	N. PARACHUTE EF03A-30 I30A 5	PR
293682	WELL	PR	10/11/2008	GW	045-15098	N. PARACHUTE EF03B-30 I30A 5	PR
293683	WELL	PR	10/14/2008	GW	045-15099	N. PARACHUTE EF06A-30 I30A 5	PR
293684	WELL	PR	10/06/2008	GW	045-15100	N. PARACHUTE EF06C-30 I30A 5	PR
293685	WELL	PR	08/09/2008	GW	045-15101	N. PARACHUTE EF07A-30 I30A 5	PR
293686	WELL	PR	10/12/2008	GW	045-15102	N. PARACHUTE EF07C-30 I30A 5	PR
293687	WELL	PR	10/03/2008	GW	045-15103	N. PARACHUTE EF16C-30 I30A 5	PR
293688	WELL	PR	10/03/2008	GW	045-15104	N. PARACHUTE EF01A-31 I30A 5	PR
293689	WELL	PR	10/13/2008	GW	045-15105	N. PARACHUTE EF01C-31 I30A 5	PR
293690	WELL	PR	09/01/2008	GW	045-15106	N. PARACHUTE EF05D-32 I30A 5	PR
293691	WELL	PR	08/09/2008	GW	045-15107	N. PARACHUTE EF14D-19 I30A 5	PR

General Comment:

[This is a summary of inspection report.](#)

[On Tuesday 01/28/2020 at approximately 1530 hours, I, Inspector Mike Longworth, conducted a field inspection at CAERUS PICEANCE LLC N.PARACHUTE-65S95W 30NESE, at Location # 335807 in Garfield County, Colorado](#)

Inspected Facilities									
Facility ID:	280531	Type:	WELL	API Number:	045-11277	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	280532	Type:	WELL	API Number:	045-11278	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	280533	Type:	WELL	API Number:	045-11279	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	280534	Type:	WELL	API Number:	045-11280	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	280535	Type:	WELL	API Number:	045-11281	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	280536	Type:	WELL	API Number:	045-11282	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	280537	Type:	WELL	API Number:	045-11283	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	280538	Type:	WELL	API Number:	045-11284	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	

Facility ID: 293553	Type: WELL	API Number: 045-15048	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 293554	Type: WELL	API Number: 045-15049	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 293555	Type: WELL	API Number: 045-15050	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 293556	Type: WELL	API Number: 045-15051	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 293557	Type: WELL	API Number: 045-15047	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 293558	Type: WELL	API Number: 045-15046	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 293559	Type: WELL	API Number: 045-15059	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 293560	Type: WELL	API Number: 045-15060	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:

Facility ID: 293680	Type: WELL	API Number: 045-15096	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 293681	Type: WELL	API Number: 045-15097	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 293682	Type: WELL	API Number: 045-15098	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 293683	Type: WELL	API Number: 045-15099	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 293684	Type: WELL	API Number: 045-15100	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 293685	Type: WELL	API Number: 045-15101	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 293686	Type: WELL	API Number: 045-15102	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 293687	Type: WELL	API Number: 045-15103	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:			Date:	

Facility ID: 293688	Type: WELL	API Number: 045-15104	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 293689	Type: WELL	API Number: 045-15105	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 293690	Type: WELL	API Number: 045-15106	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 293691	Type: WELL	API Number: 045-15107	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:			Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
Check Dams	Pass					
				Material Handling And Spill Prevention	Pass	
		Ditches	Pass			
Berms	Pass					
Ditches	Pass					
Compaction	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689704127	Inspection 689704122 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5051048