

Pit Status Evaluation Form

Pit Overview:

Pit Name: FARMER 1-34	Facility ID: 114631
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: DAVIS DRILLING INC / 22760	
Updated Operator:	
Form 15 Pit Permit Doc #: 565508	Permit Date: 10/9/1973
Related Facilities: FARMER (OWP) #1-34 (API 05-009-05188, Facility ID 205492, Loc ID 378880)	

County: BACA			
Township: 31S	Range: 43W	Section: 34	QQ: NWSE
Original Latitude/ Longitude: 37.300261 / -102.247451			
Updated Latitude/ Longitude: /			
Basis for Location Change:			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|------------------|
| <input checked="" type="checkbox"/> | Form 15 Pit Permit – Doc #: 565508 | Date: 10/9/1973 |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 485052 | Date: 9/13/1988 |
| | Doc #: 590712 | Date: 3/24/1995 |
| | Doc #: 590706 | Date: 12/13/1996 |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> | Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input checked="" type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

Well PA 8/6/1996, passed final inspection 12/13/1996.

Pit Status Review Summary:

Based on records review any pits on location were closed prior to 9/13/1988 inspection; inspections document a produced water tank on location. Associated well was plugged 8/6/1996 and passed final inspection 12/13/1996. Pit status has been changed to closed.

