

Inspection Photos
Operator: BP America
Location/API #: 067-09648
Date: 1-28-2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of southern project area from the southwestern corner facing eastward. Dense kochia debris growing above desirable vegetation.



Photo 3. View of vegetation within the project area, grasses are present beneath the weedy vegetation.



Photo 4. View of the reference area in background comprised of irrigated grass field.