

Inspection Photos
Location Name: Ward DP 1-12 Pad
Location ID: 447748



Photo 1: Wellhead Sign



Photo 2: Wellhead

Inspection Photos
Location Name: Ward DP 1-12 Pad
Location ID: 447748



Photo 3: Stained soil




Photo 4: Wellhead Sign

Inspection Photos
Location Name: Ward DP 1-12 Pad
Location ID: 447748



Photo 5: Wellhead




Photo 6: Stained soil

Inspection Photos
Location Name: Ward DP 1-12 Pad
Location ID: 447748




Photo 7: Wellhead Sign




Photo 8: Wellhead

Inspection Photos
Location Name: Ward DP 1-12 Pad
Location ID: 447748



Colorado Oil and Gas Conservation Commission
40.46721, -104.79314, 1422.8m, 232°
Jan 29, 2020 12:19:38

Photo 9: Stained Soil



Colorado Oil and Gas Conservation Commission
40.46724, -104.79311, 1422.8m, 328°
Jan 29, 2020 12:19:44

Photo 10: Wellhead Sign

Inspection Photos
Location Name: Ward DP 1-12 Pad
Location ID: 447748



Photo 11: Wellhead



Photo 12: Stained Soil

Inspection Photos
Location Name: Ward DP 1-12 Pad
Location ID: 447748



Photo 13: Wellhead Sign



Photo 14: Wellhead

Inspection Photos
Location Name: Ward DP 1-12 Pad
Location ID: 447748



Colorado Oil and Gas Conservation Commission
40.46729, -104.79314, 1421.6m, 212°
Jan 29, 2020 12:20:31

Photo 15: Stained Soil



Colorado Oil and Gas Conservation Commission
40.46731, -104.79314, 1422.7m, 300°
Jan 29, 2020 12:20:41


Photo 16: Wellhead Sign

Inspection Photos
Location Name: Ward DP 1-12 Pad
Location ID: 447748



Colorado Oil and Gas Conservation Commission
40.46731, -104.79313, 1422.4m, 250°
Jan 29, 2020 12:20:47

Photo 17: Wellhead



Colorado Oil and Gas Conservation Commission
40.46733, -104.79314, 1422.7m, 266°
Jan 29, 2020 12:20:55

Photo 18: Stained Soil

Inspection Photos
Location Name: Ward DP 1-12 Pad
Location ID: 447748



Photo 19: Wellhead Sign



Photo 20: Wellhead

Inspection Photos
Location Name: Ward DP 1-12 Pad
Location ID: 447748



Photo 21: Stained Soil



Photo 22: Wellhead Sign

Inspection Photos
Location Name: Ward DP 1-12 Pad
Location ID: 447748



Photo 23: Wellhead




Photo 24: Stained Soil

Inspection Photos
Location Name: Ward DP 1-12 Pad
Location ID: 447748




Photo 25: Wellhead Sign



Photo 26: Wellhead

Inspection Photos
Location Name: Ward DP 1-12 Pad
Location ID: 447748




Photo 27: Stained Soil



Photo 28: Wellhead Sign

Inspection Photos
Location Name: Ward DP 1-12 Pad
Location ID: 447748



Photo 29: Wellhead




Photo 30: Stained Soil

Inspection Photos
Location Name: Ward DP 1-12 Pad
Location ID: 447748




Photo 31: Wellhead Sign



Photo 32: Wellhead

Inspection Photos
Location Name: Ward DP 1-12 Pad
Location ID: 447748



Photo 33: Stained Soil




Photo 34: Wellhead Sign

Inspection Photos
Location Name: Ward DP 1-12 Pad
Location ID: 447748



Photo 35: Wellhead



Photo 36: Stained Soil