

Inspection Photos
Location Name: Pronghorn F-17 PAD
Location ID: 437059



Photo 1 – Wellheads



Photo 2 – Tank Battery

Inspection Photos
Location Name: Pronghorn F-17 PAD
Location ID: 437059




Photo 3 – Unmarked Risers between Separator and Compressor



Photo 4 – Unmarked Risers between Separator and Compressor

Inspection Photos
Location Name: Pronghorn F-17 PAD
Location ID: 437059



Photo 5 – Unmarked Risers between Separator and Compressor



Photo 6 – Unmarked Risers in Southwest Corner of location