

Ward & Son Alfred, Gay 2
121-05315

Inspection #688306864

1/29/2020

High Risk Inspection



Colorado Oil and Gas Conservation Commission

39.75203, -103.36567, 4878.6ft, 207°

01/29/2020 12:08:18 PM



Colorado Oil and Gas Conservation Commission

39.75211, -103.36573, 4855.6ft, 280°

01/29/2020 12:15:46 PM



Colorado Oil and Gas Conservation Commission
39.75201, -103.36581, 4891.7ft, 198°
01/29/2020 12:06:50 PM



Colorado Oil and Gas Conservation Commission

39.75199, -103.36573, 4898.3ft, 212°

01/29/2020 12:08:58 PM



Colorado Oil and Gas Conservation Commission

39.75204, -103.36567, 4872.0ft, 198°

01/29/2020 12:08:40 PM



Colorado Oil and Gas Conservation Commission
39.75181, -103.36538, 4875.3ft, 236°
01/29/2020 12:12:04 PM



Colorado Oil and Gas Conservation Commission
39.75199, -103.36537, 4878.6ft, 44°
01/29/2020 12:11:41 PM



Colorado Oil and Gas Conservation Commission
39.75176, -103.36504, 4875.3ft, 32°
01/29/2020 12:12:36 PM




Colorado Oil and Gas Conservation Commission
39.75177, -103.36483, 4878.6ft, 19°
01/29/2020 12:12:53 PM



Colorado Oil and Gas Conservation Commission
39.75181, -103.36476, 4872.0ft, 10°
01/29/2020 12:12:59 PM



Colorado Oil and Gas Conservation Commission
39.75179, -103.36526, 4875.3ft, 39°
01/29/2020 12:12:14 PM

A photograph of a sandy, arid landscape. A thin wire fence runs horizontally across the middle of the frame. Two vertical wooden stakes or markers are planted in the sand, one on the left and one on the right, flanking the fence. The ground is light-colored sand with some small dark spots and a few sparse, dry plants. The sky is not visible.

Colorado Oil and Gas Conservation Commission

39.75178, -103.36444, 4872.0ft, 98°

01/29/2020 12:13:24 PM