

RNPU 197-23A1H
API: 05-103-11232
Inspection: 679707149



Photo 1. Location.

RNPU 197-23A1H
API: 05-103-11232
Inspection: 679707149



Photo 2. Well head.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

RNPU 197-23A1H
API: 05-103-11232
Inspection: 679707149



39.94535, -108.24116, 6677.7ft, 353°
01/29/2020 01:55:41 PM

Photo 3. Separator & meter building.

RNPU 197-23A1H
API: 05-103-11232
Inspection: 679707149



Photo 4. Tanks.



RNPU 197-23A1H
API: 05-103-11232
Inspection: 679707149



Photo 5. Diesel container.

