

P O & G Operating LLC, Peterson 1
121-05584

Inspection #688306869

1/29/2020

Routine Inspection



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources



Colorado Oil and Gas Conservation Commission

39.78867, -103.41614, 4829.4ft, 24°

01/29/2020 01:37:22 PM



300
BOLS 9752



C.O.T.
302740
9753 H

Colorado Oil and Gas Conservation Commission
39.78868, -103.41614, 4829.4ft, 48°
01/29/2020 01:37:25 PM



Colorado Oil and Gas Conservation Commission
39.78887, -103.41619, 4816.3ft, 147°
01/29/2020 01:37:01 PM



Colorado Oil and Gas Conservation Commission
39.78854, -103.41711, 4842.5ft, 87°
01/29/2020 01:34:42 PM



Colorado Oil and Gas Conservation Commission

39.78857, -103.41704, 4862.2ft, 72°

01/29/2020 01:34:34 PM



Colorado Oil and Gas Conservation Commission

39.78849, -103.41706, 4832.7ft, 88°

01/29/2020 01:34:49 PM



Colorado Oil and Gas Conservation Commission

220°

01/29/2020 01:36:10 PM



Colorado Oil and Gas Conservation Commission
39.78887, -103.41639, 4793.3ft, 6°
01/29/2020 01:36:42 PM



Colorado Oil and Gas Conservation Commission
39.78888, -103.41626, 4813.0ft, 39°
01/29/2020 01:36:52 PM



Colorado Oil and Gas Conservation Commission
39.78888, -103.4162, 4816.3ft, 77°
01/29/2020 01:36:58 PM



Colorado Oil and Gas Conservation Commission

39.78881, -103.4162, 4819.6ft, 199°

01/29/2020 01:37:07 PM