

Interim Reclamation and Stormwater Inspection

January 28, 2020

Operator: UPLAND EXPLORATION LLC- #10701

Location ID: 462919

Inspection Document #: 697501077

Weld County, CO

SESE Section 21 T11N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Little Lady 21 /South Well Pad
Location ID: 462919



Photo 1. Photo taken from the wells, facing North. Photo illustrates Operator has backfilled around the wells to mitigate the previous safety hazard of open cellars.

Inspection Photos
Location Name: Little Lady 21 /South Well Pad
Location ID: 462919



Photo 2. Photo taken from the topsoil stockpile, facing East. Photo illustrates stormwater BMP (silt fence) around the topsoil is not in proper functioning condition.

Inspection Photos
Location Name: Little Lady 21 /South Well Pad
Location ID: 462919



Photo 3. Photo taken from the topsoil stockpile, facing East. Photo illustrates topsoil has not been properly stabilized. Equipment tracking is only a temporary stabilization BMP.

Inspection Photos
Location Name: Little Lady 21 /South Well Pad
Location ID: 462919



Photo 4. Photo taken from the southwestern location, facing South. Photo illustrates unused equipment being stored at location.



Photo 5. Photo taken from the southeastern location, facing South. Photo illustrates unused equipment and debris being stored at location.

Photo also illustrates the retention area along the eastern location for stormwater management.