

Construction and Stormwater Inspection

January 28, 2020

Operator: UPLAND EXPLORATION LLC- #10701

Location ID: 462908

Inspection Document #: 697501079

Weld County, CO

NESE Section 21 T11N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Little Lady 21 /North Well Pad
Location ID: 462908



Photo 1. Photo taken from the topsoil stockpile, facing West. Photo illustrates stormwater BMP (silt fence) around the topsoil is not in proper functioning condition.

Inspection Photos
Location Name: Little Lady 21 /North Well Pad
Location ID: 462908



Photo 2. Photo taken from the topsoil stockpile, facing West. Photo illustrates topsoil has not been properly stabilized. Equipment tracking is only a temporary stabilization BMP.

Inspection Photos
Location Name: Little Lady 21 /North Well Pad
Location ID: 462908



Photo 3. Photo taken from the topsoil stockpile, facing North. Photo illustrates Operator has not spud the location yet. Also, there is a retention around the entire well pad for stormwater management.