

Inspection Photos
Location Name: Great Western Pad 9
Location ID: 333296



Photo 1: Tank Battery Sign



Photo 2: Tank Battery

Inspection Photos
Location Name: Great Western Pad 9
Location ID: 333296



Photo 3: NFPA placard installed



Photo 4: location of where unused equipment was

Inspection Photos
Location Name: Great Western Pad 9
Location ID: 333296



Photo 5: unused equipment moved to other side of location