

Inspection Photos
Operator: BP America
Location/API #: 067-08834
Date: 1-28-2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of pipes that remain within the southeastern project area, need to be removed.



Photo 3. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with a mix of dormant perennial grasses such as sand dropseed, and rubber rabbitbrush.



Photo 4. View of the reference area in background comprised of open grass field with scattered pinyon and juniper trees, largely snow covered at this time.