

Inspection Photos
Location Name: Robertson 19-01 #1
Spill/Release Point ID #470891



Matting over bridge for equipment to access release point.



Waterway adjacent to release point.

Inspection Photos
Location Name: Robertson 19-01 #1
Spill/Release Point ID #470891



Replaced section of pipeline where release occurred.



Work progressing to reportedly abandon flow lines within trench.

Inspection Photos
Location Name: Robertson 19-01 #1
Spill/Release Point ID #470891



2" line on left side of photo and 6" with valve assembly will reportedly be abandoned.



Excavated material adjacent to water way with no containment structures in place.