

## Inspection Photos

Location Name: LARAMIE ENERGY LLC McDaniel /14-3 Pad

Location ID: 334198



**Photo #0491 from entrance to location**



**Photo #0497 1000 gallon methanol tank capacity label inaccurate.**

**Inspection Photos**  
**Location Name: LARAMIE ENERGY LLC McDaniel /14-3 Pad**  
**Location ID: 334198**



**Photo #0493 Multiple wellhead signs weathered and not legible.**



**Photo #0494 Multiple wellhead signs weathered and not legible.**

## Inspection Photos

Location Name: LARAMIE ENERGY LLC McDaniel /14-3 Pad

Location ID: 334198



**Photo #0495 Multiple wellhead signs weathered and not legible.**