

Inspection Photos

Location Name: LARAMIE ENERGY LLC McDaniel /11-11 Pad

Location ID: 334533



Photo #0498 from entrance to location



Photo #0499 Battery sign weathered and not legible.

Inspection Photos

Location Name: LARAMIE ENERGY LLC McDaniel /11-11 Pad

Location ID: 334533



Photo #0502 1000 gallon methanol tank capacity inaccurate.



Photo #0500 unused plunger.

Inspection Photos

Location Name: LARAMIE ENERGY LLC McDaniel /11-11 Pad

Location ID: 334533



Photo #0501 Unused plunger and bumper spring.