

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/30/2020

Submitted Date:

01/30/2020

Document Number:

696102060**FIELD INSPECTION FORM**

Loc ID 302641 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299791	WELL	PA	07/18/2019	OW	123-29530	WELLS RANCHUSX AA 35-09	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL** inspection.

Well(s): 1: Plugged & Abandoned | PA.

Battery: Abandoned. ALL equipment removed.

Reclamation progressing w/ mulching.

Abandoned Battery SE corner GPS coordinates: 40.439947, -104.399059

Abandoned Centralized Battery formerly served 5 Location IDs (306642, 310131, 302639, 310092, 302641).

(Well(s): 4: Temporarily Abandoned | TA ; 1: Plugged & Abandoned | PA).

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Horizontal Heated Separator

0

Comment: [Plugged & Abandoned | PA. Equipment removed.](#)Corrective Action: Date:

Type: Bradenhead

0

Comment: [Plugged & Abandoned | PA. Equipment removed.](#)Corrective Action: Date:

Type: Gas Meter Run

0

Comment: [Plugged & Abandoned | PA. Equipment removed.](#)Corrective Action: Date:

Type: Plunger Lift

0

Comment: [Plugged & Abandoned | PA. Equipment removed.](#)Corrective Action: Date:

Type: Ancillary equipment

0

Comment: [Plugged & Abandoned | PA. Equipment removed.](#)Corrective Action: Date:

Type: Emission Control Device

0

Comment: [Plugged & Abandoned | PA. Equipment removed.](#)Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				,
Comment: Plugged & Abandoned PA. Equipment removed.					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

PaintCondition: Other (Content) Other (Capacity)

Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	0				,	
Comment:				Plugged & Abandoned PA. Equipment removed.		
Corrective Action:				Date:		
Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Venting:						
Yes/No						
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 299791 Type: WELL API Number: 123-29530 Status: PA Insp. Status: PA

Workover

Comment: Plugged & Abandoned | PA.
Well appears to be cut / capped.
Form 6 doc. #402155377 indicates plugging date: 07/16/2019. Approved.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 01/30/2020 at approximately 15:28 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: WELLS RANCHUSX AA-66N63W /35NESE Location ID: 302641 Well Name: Wells RanchUSX AA35-09 API: 05-123-29530 Location County: Weld County, Colorado Weather: Mostly cloudy.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment removed. Reclamation progressing w/ mulching. Abandoned Battery SE corner GPS coordinates: 40.439947, -104.399059</p> <p>Abandoned Centralized Battery formerly served 5 Location IDs (306642, 310131, 302639, 310092, 302641). (Well(s): 4: Temporarily Abandoned TA ; 1: Plugged & Abandoned PA).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	01/30/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696102061	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5054170