

Inspection Photos

API: 05-071-08414

Operator: TIMBER CREEK OPERATING

Inspection Date: 1/30/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-08414 | Date: 1/30/2020

Inspection Photos



Photo 1. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08414 | Date: 1/30/2020

Inspection Photos



Photo 2. Well sign is posted at meter house.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08414 | Date: 1/30/2020

Inspection Photos



Photo 3. There is oily waste in the engine skid.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08414 | Date: 1/30/2020

Inspection Photos



Photo 4. There is oily waste at the engine skid at the separator.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08414 | Date: 1/30/2020

Inspection Photos



Photo 5. The muffler on the engine is broke apart causing the engine to be very loud. Needs to be maintained in good mechanical condition.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08414 | Date: 1/30/2020