

Inspection Photos
Location Name: Pronghorn 14-11-7HZ
Location ID: 426990



Photo 1 – Pumping Unit



Photo 2 – North Separators



Inspection Photos
Location Name: Pronghorn 14-11-7HZ
Location ID: 426990



Photo 3 – Southeast Separators



Photo 4 – Tanks



Inspection Photos
Location Name: Pronghorn 14-11-7HZ
Location ID: 426990




Photo 5 – Unused Methanol Tank/Pump in Northwest corner of location




Photo 6 – Unmarked Risers in the Northwest corner of location

Inspection Photos
Location Name: Pronghorn 14-11-7HZ
Location ID: 426990



Photo 6 – Unmarked Risers and the North side of Location