

Calamity Ridge 14-31  
API: 05-103-11880  
Inspection: 679707185



**Photo 1. Location.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Calamity Ridge 14-31  
API: 05-103-11880  
Inspection: 679707185



**Photo 2. Weed debris at pump jack on 1-31-2020.**



**Photo 3. Weeds at pump jack on 7-29-2019.**



Calamity Ridge 14-31  
API: 05-103-11880  
Inspection: 679707185



**Photo 4. Missing deadman marker on 1-31-2020.**



**Photo 5. Unmarked deadman.**

Calamity Ridge 14-31  
API: 05-103-11880  
Inspection: 679707185



Photo 6. Battery sign on 1-31-2020.



Photo 7. Battery sign on 7-29-2019.



Calamity Ridge 14-31  
API: 05-103-11880  
Inspection: 679707185



**Photo 8. Unused pipe on 1-31-2020.**



**Photo 9. Unused pipe on 7-29-2019.**

Calamity Ridge 14-31  
API: 05-103-11880  
Inspection: 679707185



**Photo 10. Unused propane tank on 1-31-2020.**



**Photo 11. Unused propane tank on 7-29-2019.**