

Calamity Ridge 14-15C-1N100

API: 05-103-11552

Inspection: 679707187



Photo 1. Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Calamity Ridge 14-15C-1N100
API: 05-103-11552
Inspection: 679707187



Photo 2. Pump jack weed debris on 10-31-2020.



Photo 3. Pump jack weeds on 7-29-2019.

Calamity Ridge 14-15C-1N100
API: 05-103-11552
Inspection: 679707187



Photo 4. Well head on 1-31-2020.



Photo 5. Stain soil at well head on 7-29-2019.

Calamity Ridge 14-15C-1N100
API: 05-103-11552
Inspection: 679707187



Photo 6. Tank without label on 1-31-2020.



Photo 7. Tank without label on 7-29-2020.

Calamity Ridge 14-15C-1N100
API: 05-103-11552
Inspection: 679707187



Photo 8. No apparent bird screen on tank vent on 1-31-2020.



Photo 9. No apparent bird screen on tank vent on 7-29-2019.

Calamity Ridge 14-15C-1N100
API: 05-103-11552
Inspection: 679707187



Photo 10. Storm water reeling off hillside on 1-31-2020.



Photo 11. Storm water reeling off hillside on 7-29-2019.

Calamity Ridge 14-15C-1N100
API: 05-103-11552
Inspection: 679707187



Photo 12. "911" missing on battery sign on 1-31-2020.




Photo 13. "911" missing on battery sign on 7-29-2019.

Calamity Ridge 14-15C-1N100
API: 05-103-11552
Inspection: 679707187



Photo 14. Damaged culvert on 1-31-2020.



Photo 15. Damaged culver on 7-29-2019.

Calamity Ridge 14-15C-1N100
API: 05-103-11552
Inspection: 679707187



Photo 16. Deadman marker not present on 1-31-2020.



Photo 17. Fallen deadman marker on 7-29-2019.

Calamity Ridge 14-15C-1N100
API: 05-103-11552
Inspection: 679707187



Photo 18. Open tank hatch on permanent tank.



Photo 19. Open tank hatch on portable tank.