

Calamity Ridge Unit 4401D A23 1N100

API: 05-103-10561

Inspection: 679707189



Photo 1. Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Calamity Ridge Unit 4401D A23 1N100
API: 05-103-10561
Inspection: 679707189



Photo 3. Tank label on 7-30-2019.

Calamity Ridge Unit 4401D A23 1N100
API: 05-103-10561
Inspection: 679707189



Photo 4. Tank line hole on 1-31-2020.



Photo 5. Tank liner hole on 7-30-2019.

Calamity Ridge Unit 4401D A23 1N100
API: 05-103-10561
Inspection: 679707189



Photo 6. Missing deadman marker on 1-31-2020.



Photo 7. Unmarked deadman on 7-30-2019.

Calamity Ridge Unit 4401D A23 1N100
API: 05-103-10561
Inspection: 679707189



Photo 8. Valve can on 1-31-2020.



Photo 9. Valve can on 7-30-2019.

Calamity Ridge Unit 4401D A23 1N100
API: 05-103-10561
Inspection: 679707189



Photo 10. Battery sign on 1-31-2020.



Photo 11. Battery sign on 7-30-2019.

Calamity Ridge Unit 4401D A23 1N100
API: 05-103-10561
Inspection: 679707189



Photo 12. Pumpjack weed debris on 1-31-2020.



Photo 13. Pumpjack weeds on 7-30-2019.

Calamity Ridge Unit 4401D A23 1N100
API: 05-103-10561
Inspection: 679707189



Photo 14. Pump jack missing sign on 1-31-2020.



Photo 15. Pump jack missing sign on 7-30-2019.