


**Inspection Photos**  
**Location Name: Anschutz Windmill 13-23H PAD**  
**Location ID: 421762**



**Photo 1 – Unmarked Riser North of Heater Treaters**



**Photo 2 – Unmarked Riser North of Heater Treaters**

**Inspection Photos**  
**Location Name: Anschutz Windmill 13-23H PAD**  
**Location ID: 421762**



**Photo 3 – Unused Secondary Containment**

**Photo 2 – Unmarked Riser North of Heater Treaters**