

Well Name: Olson Smith GU 2, IGE 127 **API #** 05-067-07911 05-067-09545
Inspection Number: 693901375

Corrective Action: Unused risers need lockout/tagout labelling within 24 hours (1/28/2020) and to be removed within 30 days (2/26/2020).

Correction Action Due: 1/28/2020

Action Completed: 1/27/2020

Action Taken: Installed lockout/tagout on risers

Corrective Action:

Correction Action Due: 2/26/2020

Action Completed: 2/3/2020

Action Taken: Removed risers

