

Inspection Photos

Location Name: PARADISE FEDERAL 13-8 TR CA DATE 2-1-20

API#: 05-071-07946

INSP. #: 695102104



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN

Inspection Photos

Location Name: PARADISE FEDERAL 13-8 TR CA DATE 2-27-20

API#: 05-071-07946

INSP. #: 695102104



Colorado Oil & Gas Conservation Commission
37.27103, -104.80902, 2436.0m, 182°
2020/01/27 13:21:35

PHOTO 3: PRIME MOVER ON PUMPJACK IS LEAKING, OIL IS RUNNING OFF PUMPJACK BASE ON ONTO SOIL. Conduct maintenance on equipment (REPAIR LEAKS), cleanup stained material and review self inspection processes. CA DATE FOR CLEANUP OF IMPACTED SOIL 2-1-20. 30 DAYS TO REPAIR LEAKS ON PUMPJACK MOTOR.