

2nd well

WELL SITE INSPECTION FORM



00251250

C

WELL NAME Lee 3505

API NUMBER 05 - 081 - 6721

OPERATOR Cockrell

PERMIT NUMBER 20-425

LOCATION SUNW 35, 7N, 91W

COUNTY Maffett

FIELD Craig

INSPECTOR KOB

AL/PA/DA INSPECTION RESULTS:

WELL STATUS:

PASS(Y) FAIL(N) DATE 6/6/90

FN FD ✓ WO

DATE OF INSPECTION BEFORE/DURING DRILLING

CASING SIZE DEPTH SET CMT VOL WOC

CONSISTENT WITH APD CASING PROGRAM? RETURNS

RIG BOP'S CONTACT

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION 6/6/90

PIPE SET? yes COMPLETION RIG/ACTIVITY None

DRILLING PITS: CLOSED OPEN ✓ WELLHEAD SYSTEM INSTALLED yes

TANK ID: YES NO NA ✓ WELL SIGN: YES NO ✓

SKIM PIT: gal TANKS: () bbls

EQUIPMENT No

BRADENHEAD PRESSURE FLUID: NO YES TYPE

METER RUN: YES NO WELL STATUS: PR TA ✓ SI WELL CAT 3- B

AL/PA/DA INSPECTION

DATE PLUGGED:

DATE PERMIT EXPIRED:

HOLE PLUGGED: YES NO

PITS BACKFILLED: YES NO

MATERIAL BURIED: YES NO NA

SITE CLEAN: YES NO

BOND RELEASE OK: YES NO FED

HOLE MARKER: YES NO

DATE OF SAFETY/STATUS INSPECTION

COMMENTS Noeds fence around pit, Mouse hole
and 2nd notice for sign

Spoke to Tom Boyd @ Cockrell about
deficiencies. 6/6/90