

Location ID: 320247

5-28-14	1.350	5-28-14	5-28-14
5-28-14	R/R Temp.	A55864	



Photo #2 stained soil under separator

Inspection Photos
Location Name: Rueble ET AL #1-3
Location ID: 320247



Photo #3 bull plug missing from load out line



Photo #4 tanks

Inspection Photos
Location Name: Rueble ET AL #1-3
Location ID: 320247



Photo #5 meter run and separator



Photo #6 wellhead