

Inspection Photos
Location Name: John A Kunzman 1
Location ID: 317729



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: John A Kunzman 1
Location ID: 317729



Photo 3 Unused equipment, PJ base hog fence and cement pads

Photo 4 unused equipment horse head

Inspection Photos
Location Name: John A Kunzman 1
Location ID: 317729



Photo 5 dead weeds around location