

Inspection Photos  
Location Name: Johnson, Rolland D unit 1 TB  
Location ID: 336098



Photo 1 TB signs

Photo 2 TB Shared berm with Kerr McGee

**Inspection Photos**  
**Location Name: Johnson, Rolland D unit 1 TB**  
**Location ID: 336098**



**Photo 3 Horizontal Heated separators**

**Photo 4 ECD**

**Inspection Photos**  
**Location Name: Johnson, Rolland D unit 1 TB**  
**Location ID: 336098**



**Photo 5 dead weeds around old manifold**

**Photo 6 Gas Meter Run**