

# *Inspection Photos*

Loc#311695

*Operator: Ursa*

*Inspection Number: 692401851*

*Inspection Date: 1/24/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
View of Location to Northeast and interim area.

January 24, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Ursa Gentry Loc#311695



Photo#2 :

Weedy area of berm and what maybe topsoil where it appears seeding failed.

January 24, 2020





Photo#3:  
Weedy area behind equipment.



Photo#4:  
Weedy portion of Interim Rec area.

January 24, 2020



Photo#5:  
XX Well API#045-15270.

January 24, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Ursa Gentry Loc#311695