

# *Inspection Photos*

Loc#335550

*Operator: Ursa*

*Inspection Number: 692401853*

*Inspection Date: 1/24/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to East and interim area.

January 24, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Ursa Dixon Loc#335550



Photo#2:  
Interim areas, Kochia and Cheat grass notable.

January 24, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Ursa Dixon Loc#335550





**Photo#3:**  
Escape boards need to be adjusted or Cellars fully covered.



**Photo#4:**  
Escape boards need to be adjusted or Cellars fully covered.

January 24, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Ursa Dixon Loc#335550