

**Inspection Photos**  
**Location Name: Wilson PC GQ 02-04 Tank Battery**  
**Location ID: 461134**



**Photo 1 – Tank Battery**



**Photo 2 – Produced Water Tank missing Capacity and NFPA label is fading. Unused Loadline and Loadline bucket.**

**Inspection Photos**  
**Location Name: Wilson PC GQ 02-04 Tank Battery**  
**Location ID: 461134**



**Photo 3 – Unmarked 2” Riser SE Corner of Tank Berm**

**Photo 4 – Stained Soil at Heater Treater**