

Inspection Photos

1/31/2020

Operator: TWIN ARROW INC - 90700

Location ID: 398268

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TWIN ARROW INC - 90700
Location ID: 398268



Photo 1: Photo taken from the south end of the Location, facing North. Location is "AL", photo shows Location does not appear to have been constructed or well drilled.



Photo 2: Photo taken from the Location, facing north. Photo shows metal stake used as a well marker remains. Marker will need to be removed.