

# Inspection Photos

1/31/2020

Operator: TWIN ARROW INC - 90700

Location ID: 398269

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: TWIN ARROW INC - 90700  
Location ID: 398269



**Photo 1:** Photo taken from the west end of the Location, facing east. Location is “AL”, photo shows Location does not appear to have been constructed or well drilled.



**Photo 2:** Photo taken from the Location, facing east. Photo shows metal stake used as a well marker remains. Marker will need to be removed.