


**Inspection Photos**  
**Location Name: Mustang 12-26 Pad**  
**Location ID: 452874**



**Photo #1 Location**



**Photo #2 Well**

Inspection Photos  
Location Name: Mustang 12-26 Pad  
Location ID: 452874



Colorado Oil and Gas Conservation Commission  
40.28582, -104.41414, 4691.6ft, 313°  
02/11/2020 07:34:08 AM



Colorado Oil and Gas Conservation Commission  
40.28597, -104.41418, 4689.7ft, 340°  
02/11/2020 07:34:34 AM

Photo #3 Tank Battery

Photo #4 Separator & ECD

**Inspection Photos**  
**Location Name: Mustang 12-26 Pad**  
**Location ID: 452874**



**Photo #5 Unused Equipment**

**Photo #6 Stained Soil in pan**

**Inspection Photos**  
**Location Name: Mustang 12-26 Pad**  
**Location ID: 452874**



**Photo #7 Generator & Dehydrator**

**Photo #8 NGL Storage tank**

Inspection Photos  
Location Name: Mustang 12-26 Pad  
Location ID: 452874



**Photo #9 Appears to be grounded**



**Photo #10 Appears to be grounded**