

Inspection Photos
Location Name: Mustang 44-22 Pad
Location ID: 450205



Photo #1 Location



Photo #2 Well

Inspection Photos
Location Name: Mustang 44-22 Pad
Location ID: 450205



Photo #3 Tank Battery

Photo #4 Separator & ECD

Inspection Photos
Location Name: Mustang 44-22 Pad
Location ID: 450205



Colorado Oil and Gas Conservation Commission
40.29381, -104.4164, 4714.3ft, 340°
02/11/2020 08:27:29 AM

Photo #5 Trash



Colorado Oil and Gas Conservation Commission
40.29407, -104.41577, 4721.2ft, 280°
02/11/2020 08:38:31 AM

Photo #6 Trash

Inspection Photos
Location Name: Mustang 44-22 Pad
Location ID: 450205



Photo #7 Unused Equipment



Photo #8 Unused Equipment

Inspection Photos
Location Name: Mustang 44-22 Pad
Location ID: 450205



Photo #9 Generator, Dehydrator & NGL Storage Tank



Photo #10 Appears to be grounded