

Inspection Photos
Location Name: Mustang U-22 Pad
Location ID: 452873



Photo #1 Location

Inspection Photos
Location Name: Mustang U-22 Pad
Location ID: 452873



Photo #2 Well



Photo #3 Tank Battery

Inspection Photos
Location Name: Mustang U-22 Pad
Location ID: 452873



Photo #4 Separator & ECD



Photo #5 Unused Equipment

Inspection Photos
Location Name: Mustang U-22 Pad
Location ID: 452873



Photo #6 Generator, Dehydrator & NGL Storage Tank

Photo #7 Appears to be grounded

Inspection Photos
Location Name: Mustang U-22 Pad
Location ID: 452873



Colorado Oil and Gas Conservation Commission
40.30494, -104.41685, 4659.7ft, 291°
02/11/2020 09:18:13 AM



Colorado Oil and Gas Conservation Commission
40.3049, -104.4168, 4680.5ft, 262°
02/11/2020 09:27:18 AM

Photo #8 Tore Secondary Containment/ duck pond

Photo #9 Tore Secondary Containment/ duck pond