

Inspection Photos
Location Name: Sater CC18-72-1HN Pad
Location ID: 434152



Photo #1 Location

Inspection Photos
Location Name: Sater CC18-72-1HN Pad
Location ID: 434152



Photo #2 Well & Sign



Photo #3 Well & Sign



Inspection Photos
Location Name: Sater CC18-72-1HN Pad
Location ID: 434152



Photo #4 Well & Sign



Photo #5 Maintenance tank oil stain down the side.

Inspection Photos
Location Name: Sater CC18-72-1HN Pad
Location ID: 434152



Photo #6 Stain soil



Photo #7 Broken thief hatch latch