

Inspection Photos
Location Name: Cox 1161 34-42
Location ID: 415946




Photo 1 – Pumping Unit

Photo 2 – Well Sign

Inspection Photos
Location Name: Cox 1161 34-42
Location ID: 415946




Photo 3 – Unused Stand and Containment. Stained Soil at Exhaust

Photo 4 – Unused Wellhead parts