

**Inspection Photos**  
**Operator: BP America**  
**Location #: 311980**  
**Date: 1-31-2020**



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Vegetation is largely in a grazed/dormant condition at this time, although perennial grasses are established similar to reference area vegetation.



Photo 3. View of Russian knapweeds within the eastern project area. Approximately 200 individuals observed.



Photo 4. View of the reference area, comprised of pinyon juniper woodland with herbaceous understory, largely in a grazed/dormant vegetative condition.