

# Inspection Photos

API: 071-08657

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 2/10/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08657 | Date: 2/10/2020

## Inspection Photos



**Photo 1.** Facing toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08657 | Date: 2/10/2020

## Inspection Photos



**Photo 2.** There is a water leak at the PR well which needs to be repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08657 | Date: 2/10/2020

## Inspection Photos



**Photo 3.** Well sign is posted at backside of meter shed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08657 | Date: 2/10/2020

## Inspection Photos



**Photo 4.** Facing toward the TA well and pit area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08657 | Date: 2/10/2020