

# Inspection Photos

API: 071-09252

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 2/10/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09252 | Date: 2/10/2020

## Inspection Photos



**Photo 1.** Facing southwest at the beginning of the access road which has not been reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09252 | Date: 2/10/2020

## Inspection Photos



**Photo 2.** Facing west along the access road which has not been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09252 | Date: 2/10/2020

## Inspection Photos



**Photo 3.** Facing northwest toward the location. The location has not been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09252 | Date: 2/10/2020

## Inspection Photos



**Photo 4.** Facing east toward the fill slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09252 | Date: 2/10/2020

## Inspection Photos



**Photo 5.** North side of the location facing toward the fill slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09252 | Date: 2/10/2020

## Inspection Photos



**Photo 6.** East side of the location facing west.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09252 | Date: 2/10/2020