

Inspection Photos
Location Name: Herbst C 34-29
API # 05-123-29949



Photo #1 Well, Sign, Weeds & Tore down gate



Photo #2 Weeds & Tore down gate