

Inspection Photos
Location Name:North Washington 2-23
Location ID: 336041



Photo#1 Separators/ECD's/Gas Meters



Photo#2 Tank Battery

Corrective Action: Dead Weeds all around inside and outside of tanks.

Inspection Photos
Location Name:North Washington 2-23
Location ID: 336041



Photo#3 Wellhead