


**Inspection Photos**  
**Location Name: Ptasnik LC20-75HN**  
**Location ID: 422561**



**Photo 1 – Wellhead**




**Photo 2 – Tank Battery**

**Inspection Photos**  
**Location Name: Ptasnik LC20-75HN**  
**Location ID: 422561**



**Photo 3 – Unused Chemical Tank and Containment. See photos. If still in use, please stand Chemical Tank backup and install wildlife netting on Secondary Containment.**



**Photo 4 – 1<sup>st</sup> and 3<sup>rd</sup> Tanks from the North missing Capacity**

