

Inspection Photos
Location Name: Castor Federal LC23-62HN
Location ID: 431062



Photo 1 – Tank Battery



Photo 2 – Tank Missing NFPA Label



Inspection Photos
Location Name: Castor Federal LC23-62HN
Location ID: 431062




Photo 3 – Missing Capacity



Photo 4 – Unused Wellhead Parts



Inspection Photos
Location Name: Castor Federal LC23-62HN
Location ID: 431062



Photo 5 – Unused Chemical Tank



Photo 6 – Unused Wellhead parts and Unused Chemical Tank

