

Inspection Photos
Location Name: Antelope J-19 PAD
Location ID: 430139



Photo 1 – Wellheads



Photo 2 – Separators



Inspection Photos
Location Name: Antelope J-19 PAD
Location ID: 430139



Photo 3 – Tanks



Photo 4 – Unused pipe. South of Compressors

Inspection Photos
Location Name: Antelope J-19 PAD
Location ID: 430139



Photo 5 – 2” Unmarked Risers south of Compressor



Photo 5 – Unmarked 1” Riser west of Compressor

Inspection Photos
Location Name: Antelope J-19 PAD
Location ID: 430139



Photo 6 – Unmarked 1" Riser and trash west of Compressor