

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/19/2020

Submitted Date:

02/19/2020

Document Number:

696301388

**FIELD INSPECTION FORM**

Loc ID 413543 Inspector Name: PETRIE, ERICA On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 8960  
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY  
Address: 410 17TH STREET SUITE #1400  
City: DENVER State: CO Zip: 80202

**Findings:**

- 12 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
,		EHSRC@bonanzacrck.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297454	WELL	TA	03/03/2019	OW	123-27148	Antelope 41-19	TA
412531	WELL	TA	09/01/2019	OW	123-30509	ANTELOPE 42-19	TA
420770	WELL	TA	03/03/2019	OW	123-32712	Antelope 19G	TA
427851	WELL	TA	03/03/2019	OW	123-35126	Antelope P-19	TA
427853	WELL	TA	03/03/2019	OW	123-35128	Antelope W-19	TA
427856	WELL	TA	02/22/2019	OW	123-35130	Antelope R-19	TA
427863	WELL	TA	02/23/2019	OW	123-35135	Antelope X-19	TA

**General Comment:**

Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate (x7)		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained Soil at the 41-19 Wellhead, see photo 2		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e."		Date: <u>03/06/2020</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Plunger Lift			# 7
Comment:			
Corrective Action:			Date:
Type: Bradenhead			# 7
Comment:			Appear to be plumbed to surface
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	297454	Type:	WELL	API Number:	123-27148	Status:	TA	Insp. Status:	TA
<b>Idle Well</b>									
Purpose:	<input type="checkbox"/> Shut In	<input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: _____						
Comment:	TA								
Corrective Action:					Date: _____				
Facility ID:	412531	Type:	WELL	API Number:	123-30509	Status:	TA	Insp. Status:	TA
<b>Idle Well</b>									
Purpose:	<input type="checkbox"/> Shut In	<input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: _____						
Comment:	TA								
Corrective Action:					Date: _____				
Facility ID:	420770	Type:	WELL	API Number:	123-32712	Status:	TA	Insp. Status:	TA
<b>Idle Well</b>									
Purpose:	<input type="checkbox"/> Shut In	<input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: _____						
Comment:	TA								
Corrective Action:					Date: _____				
Facility ID:	427851	Type:	WELL	API Number:	123-35126	Status:	TA	Insp. Status:	TA
<b>Idle Well</b>									
Purpose:	<input type="checkbox"/> Shut In	<input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: _____						
Comment:	TA								
Corrective Action:					Date: _____				
Facility ID:	427853	Type:	WELL	API Number:	123-35128	Status:	TA	Insp. Status:	TA
<b>Idle Well</b>									
Purpose:	<input type="checkbox"/> Shut In	<input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: _____						
Comment:	TA								
Corrective Action:					Date: _____				
Facility ID:	427856	Type:	WELL	API Number:	123-35130	Status:	TA	Insp. Status:	TA
<b>Idle Well</b>									
Purpose:	<input type="checkbox"/> Shut In	<input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: _____						
Comment:	TA								
Corrective Action:					Date: _____				
Facility ID:	427863	Type:	WELL	API Number:	123-35135	Status:	TA	Insp. Status:	TA

**Idle Well**

Purpose:  Shut In       Temporarily Abandoned      Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Routine Field Inspection. Stained Soil at the 41-19 Wellhead, see photos. Comply with Rule 907.e. Corrective Action Date 03.06.2020</a>	petrie	02/19/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696301389	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5071728">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5071728</a>