

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/19/2020

Submitted Date:

02/19/2020

Document Number:

699301148

FIELD INSPECTION FORM

Loc ID 322976 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 1801 CALIFORNIA STREET #2500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244563	WELL	TA	07/01/2019	OW	123-12358	RASMUSSEN H UNIT 1	TA

General Comment:

(This area is currently blank for general comments.)

Location

Overall Good:

Signs/Marker:

Type	DRILLING/RECOMP		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 244563 Type: WELL API Number: 123-12358 Status: TA Insp. Status: TA

Cement

Cement Contractor

Contractor Name: Swabbco Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 5000 Cement Volume (sx): 85 sxs

Good Return During Job: YES Cement Type: G neat

Comment: Swabbco Workover crew TOO H stand back and laying down tubing, pick up retainer TIH and set a retainer @ 5000' and pump a squeeze 85 sxs total with 10 on top of retainer @ 4975'. TOO H stand back tubing to prep for more perms in the morning.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 2/19/2020 at approximately 1230 hrs to 1700 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Crestone Peak Resources location: Rasmussen H unit #1 at API #05-123-12358 in Weld County Colorado. While there, I observed Plug & Abandon operation. Form 42 Doc. # 402070268 was submitted on 6-11-2019 and Form 6 Doc # 402060647 was submitted on 6-5-2019 During this inspection I observed the Swabbco Workover crew TOO H stand back and laying down tubing, pick up retainer TIH and set retainer @ 4975' . Swabbco Cement crew pump a squeeze @ 5000', 75 sxs G neat cement with 10 on top of retainer 85 sxs total. TOO H stand back tubing to prep for more perms in the morning. During this inspection no compliance issues were observed: See attached photos. Location is snow covered, weather is snowing and overcast. I spoke with Carl Rejas Consulting representative for Crestone Peak Resources during the days operations . Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	02/19/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699301149	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5072121