

Location Name: – Caerus Washco LLC – Church Pits – Rem #4301
Inspection Date: 02/18/2020



Photo # 1 – View west at areas of limited or no vegetation



Location Name: – Caerus Washco LLC – Church Pits – Rem #4301
Inspection Date: 02/18/2020



Photo # 2 – Areas of limited or no vegetation



Location Name: – Caerus Washco LLC – Church Pits – Rem #4301
Inspection Date: 02/18/2020



Photo # 3 – Areas of limited or no vegetation



Location Name: – Caerus Washco LLC – Church Pits – Rem #4301
Inspection Date: 02/18/2020



Photo # 4 – Areas of limited or no vegetation



Location Name: – Caerus Washco LLC – Church Pits – Rem #4301
Inspection Date: 02/18/2020



Photo # 5 – Areas of limited or no vegetation



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Caerus Washco LLC – Church Pits – Rem #4301
Inspection Date: 02/18/2020



Photo # 6 – Areas of limited or no vegetation



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Caerus Washco LLC – Church Pits – Rem #4301
Inspection Date: 02/18/2020



Photo # 7 – Areas of limited or no vegetation



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Caerus Washco LLC – Church Pits – Rem #4301
Inspection Date: 02/18/2020



Photo # 8 – Areas of limited or no vegetation

Location Name: – Caerus Washco LLC – Church Pits – Rem #4301
Inspection Date: 02/18/2020



Photo # 9 – Areas of limited or no vegetation

Location Name: – Caerus Washco LLC – Church Pits – Rem #4301
Inspection Date: 02/18/2020



Photo # 10 – Areas of limited or no vegetation